

KEY FOR SLUDGE LAB TESTS

Ash	Ash		HEAVY METALS
B	Boron	Al	Aluminum
Ca	Calcium	As	Arsenic
Cl	Chloride	Ba	Barium
Cu	Copper	Cd	Cadmium
EC	Electrical Conductivity	Cr	Chromium
Fe	Iron	Co	Cobalt
H2O	Moisture	Pb	Lead
K	Potassium	Hg	Mercury
Mg	Magnesium	Mo	Molybdenum
Mn	Manganese	Ni	Nickel
Na	Sodium	Se	Selenium
NH4-N	Ammonium-Nitrogen	Si	Silica
NO3-N	Nitrate-Nitrogen	Ag	Silver
Organic N	Organic Nitrogen	U	Uranium
P	Phosphorus	V	Vanadium
pH	pH		
S	Sulfur		
Total-N	Total Nitrogen		
Zn	Zinc		